

GREENDALE CREEK FLOOD STUDY

DRAFT





Level 2, 160 Clarence Street
Sydney, NSW, 2000

Tel: (02) 9299 2855
Fax: (02) 9262 6208
Email: wma@wmawater.com.au
Web: www.wmawater.com.au

GREENDALE CREEK FLOOD STUDY

DRAFT
FEBRUARY 2022

Project Greendale Creek Flood Study		Project Number 118094	
Client Northern Beaches Council		Client's Representative Valerie Tulk Duncan Howley	
Authors Michael Reeves Ben Oakley Rhys Hardwick Jones		Prepared by TO BE SIGNED FOR FINAL REPORT	
Date 21 February 2022		Verified by TO BE SIGNED FOR FINAL REPORT	
Revision	Description	Distribution	Date
1	1st Draft Report	Northern Beaches Council	Jan 2020
2	Public Exhibition Draft Report	Northern Beaches Council	Feb 2022

GREENDALE CREEK FLOOD STUDY

TABLE OF CONTENTS

	PAGE
FOREWORD	i
EXECUTIVE SUMMARY	ii
1. INTRODUCTION	1
1.1. Background	1
1.2. Scope of Study	1
2. BACKGROUND	2
2.1. Study Area	2
2.2. Curl Curl Lagoon.....	2
2.3. Historical Flooding	3
2.4. Previous Studies.....	3
2.4.1. Dee Why Lagoon and Curl Curl Lagoon Flood Studies	3
2.4.2. Dee Why Lagoon and Curl Curl Lagoon Floodplain Risk Management Study & Plan	4
3. AVAILABLE DATA	5
3.1. Overview.....	5
3.2. Data Sources	5
3.3. Topographic Data	6
3.4. Hydraulic Structures.....	6
3.5. Bathymetric Survey.....	7
3.6. Pit and Pipe Data	7
3.7. NSW Tidal Planes Analysis.....	7
3.8. Stream Gauge Data	8
3.9. Historical Rainfall Data.....	9
3.9.1. Overview	9
3.9.2. Rainfall Stations.....	10
3.9.3. Analysis of November 2018 Rainfall Event	10
4. COMMUNITY CONSULTATION	12
4.1. Overview.....	12
4.2. Community Responses	12
4.3. Public Exhibition	13
5. HYDROLOGIC MODEL	15
5.1. Introduction	15
5.2. Sub-catchment delineation.....	15
5.3. Impervious Surface Area	15
5.4. Rainfall Losses and WBNM Lag Parameters	16
6. HYDRAULIC MODEL	18
6.1. Introduction	18

6.2.	Model Extent and Grid Resolution.....	18
6.3.	Model Topography.....	19
6.4.	Boundary Conditions.....	19
6.4.1.	Inflow Boundaries	19
6.4.2.	Downstream Boundaries.....	19
6.5.	Surface Roughness	19
6.6.	Hydraulic Structures.....	20
6.6.1.	Buildings.....	20
6.6.2.	Fencing and Obstructions	20
6.6.3.	Bridges and Culverts	21
6.6.4.	Surface and Sub-Surface Drainage Network	21
6.6.5.	Inlet Pits.....	22
6.6.6.	Road Kerbs and Gutters	22
6.6.7.	Harbord Road GPT	22
6.6.8.	Footbridge and Rock Weir	23
6.6.9.	The Kilns	24
6.6.10.	Brookvale Oval	25
6.6.11.	St Augustine's School.....	25
6.6.12.	Curl Curl Lagoon Entrance	26
7.	MODEL CALIBRATION	27
7.1.	Approach	27
7.2.	Hydraulic Model Calibration	27
7.3.	Validation.....	29
7.4.	Summary	31
8.	DESIGN EVENT MODELLING	33
8.1.	Overview.....	33
8.2.	ARR2019 IFD	33
8.3.	Temporal Patterns	33
8.4.	Critical Duration	34
8.5.	Design Rainfall Losses and Pre-Burst Rainfall	35
8.6.	Areal Reduction Factors	36
8.7.	Blockage.....	36
8.8.	Ocean Level Boundary Conditions.....	37
8.9.	Initial Water Level Assumptions	38
9.	DESIGN FLOOD MODELLING RESULTS	39
9.1.	Flood Behaviour.....	39
9.2.	Tables of Peak Flood Levels, Depths and Flows.....	40
9.3.	Hydraulic Hazard Categorisation.....	43
9.3.1.	Floodplain Development Manual.....	44
9.3.2.	Australian Disaster Resilience Handbook Collection.....	44
9.4.	Flood Function	46
9.5.	Information to Support Decisions on Activities in the Floodplain and Managing Flood Risk	47
9.5.1.	Road Inundation	47
9.5.2.	Pipe Capacity Assessment	47
9.5.3.	Flood Planning Constraint Categories.....	47

9.5.4.	Flood Planning Area	49
9.5.4.1.	Background	49
9.5.4.2.	Methodology	49
9.6.	Descriptions of Hot Spots.....	50
9.6.1.	The Kilns to St Augustine's College	51
9.6.2.	St Augustine's College to Pittwater Road.....	53
9.6.3.	Pittwater Road to Winbourne Road.....	53
9.6.4.	Winbourne Road to Harbord Road.....	54
9.6.5.	Pittwater Road at West Street.....	55
9.6.6.	Pittwater Road at West Street.....	56
9.6.7.	Playing Fields South of Greendale Creek	57
9.6.8.	Harbord Park to Bennett Street.....	58
9.6.9.	Mitchell Road Sag Point near Powells Road	59
10.	SENSITIVITY ANALYSIS	60
10.1.	Overview.....	60
10.2.	Catchment Lag Parameter	61
10.3.	Rainfall Losses	62
10.4.	Roughness Variations.....	63
10.5.	Blockage Variations	64
10.6.	Energy Loss Variations	67
10.7.	Initial Water Level Variations.....	68
11.	CLIMATE CHANGE IMPACTS	69
12.	ACKNOWLEDGEMENTS.....	72
13.	REFERENCES	73
14.	GLOSSARY.....	75
14.1.	List of Acronyms	75
14.2.	Terminology of Flood Risk	75
14.3.	Glossary of Terms	77
APPENDIX A.	ARR2019 Metadata	A.1
APPENDIX B.	Catchment Photographs	B.2
APPENDIX C.	November 2018 Calibration Event Results	C.1
APPENDIX D.	Design Flood Depths, Levels and Velocities	D.2
APPENDIX E.	Hydraulic Hazard and Flood Function.....	E.3
APPENDIX F.	Road Overtopping Information	F.4
APPENDIX G.	Climate Change Impacts	G.5

LIST OF DIAGRAMS

Diagram 1: Tidal Planes Diagram	8
Diagram 2: Temporal Pattern Bins	34
Diagram 3: Provisional “L2” Hydraulic Hazard Categories (Reference 5)	44
Diagram 4: General Flood Hazard Vulnerability Curves (ADR)	45
Diagram 5: Legend for Hot Spot Diagrams	50
Diagram 6: “The Kilns” at 48A Consul Road	51
Diagram 7: Flow path from the Kilns to St Augustine’s College	52
Diagram 8: Flow path from St Augustine’s College to Pittwater Road	53
Diagram 9: Flow path from Pittwater Road to Winbourne Road	54
Diagram 10: Sag Point at eastern end of Chard Road	54
Diagram 11: Overland flow paths in Industrial Area near Harbord Road	55
Diagram 12: Overland flow paths at Pittwater Road near West Street	56
Diagram 13: Overland flow paths from Pitt Road to Abbott Road	56
Diagram 14: Low-lying terrain between Stirgess Avenue and Weldon Oval / Stirgess Reserve	57
Diagram 15: Low-lying terrain between Bennett Street and Cricket Ovals	57
Diagram 16: Overland flow path from Harbord Park to Bennett Street	58
Diagram 17: Mitchell Road Sag Point near Powells Road	59

LIST OF PHOTOGRAPHS

Photo 1: The Kilns (March 2013)	12
Photo 2: Flooding near Unit 6, The Kilns (2014)	12
Photo 3: Stirgess Reserve (March 2011)	13
Photo 4: Flooding at The Kilns (September 2013)	13
Photo 5: Griffin Road bridge (looking upstream)	21
Photo 6: GPT (looking upstream at Harbord Road culverts)	23
Photo 7: GPT trash rack (looking downstream)	23
Photo 8: Rock Weir (looking downstream from western pedestrian footbridge)	23
Photo 9: Western pedestrian footbridge (looking upstream)	23
Photo 10: Typical semi-natural channel section at the Kilns (looking downstream)	24
Photo 11: The Kilns channel through property (looking downstream)	24
Photo 12: Western stormwater channel at The Kilns (looking downstream)	24
Photo 13: Inlet grate (The Kilns, western channel)	24
Photo 14: Brookvale Oval (eastern bund looking north)	25
Photo 15: Brookvale Oval (eastern bund looking south)	25
Photo 16: St Augustine’s College flow path	25
Photo 17: Curl Curl Lagoon entrance	26

LIST OF TABLES

Table 1: Data Sources	6
Table 2: Tidal Planes Analysis Results (MHL, 2012)	8
Table 3: Pluviometer Rainfall Stations	10
Table 4: Daily Rainfall Depths (mm) for the November 2018 Event	11
Table 5: ARR2019 Effective Impervious Area Estimation	16
Table 6: Adopted WBNM Parameters for Calibration	17
Table 7: Mannings 'n' values adopted in TUFLOW	20
Table 8: Adopted Parameters of Curl Curl Lagoon Entrance	28
Table 9: Comparison of Modelled and Recorded Flood Levels	28
Table 10: Validation of Modelling from Community Responses and Customer Complaints	29
Table 11: Average Design Rainfall Depths (mm)	33
Table 12: Design Event Critical Durations and Representative Temporal Patterns	35
Table 13: Areal Reduction Factors for the Design Storm Events	36
Table 14: Design blockage factors applied at mainstream hydraulic structures	37
Table 15: Catchment Rainfall Event and Corresponding Design Berm Height	38
Table 16: Peak Flood Levels (mAHD) at Key Locations	41
Table 17: Peak Flood Depths (m) at Key Locations	42
Table 18: Peak Flood Flows (m ³ /s) at Key Locations	43
Table 19: Overview of Sensitivity Analyses	60
Table 20: Sensitivity of 1% AEP Peak Flow (m ³ /s) to the Lag Factor	61
Table 21: Sensitivity of 1% AEP peak flows (m ³ /s) to rainfall losses	62
Table 22: Roughness Sensitivity Analysis – Change in Peak Flood Level (m)	63
Table 23: Pit Blockage Sensitivity Analysis – Change in Peak Flood Level (m)	64
Table 24: Culvert / Bridge Blockage Sensitivity – 5% AEP Change in Peak Flood Level (m)	65
Table 25: Culvert / Bridge Blockage Sensitivity – 1% AEP Change in Peak Flood Level (m)	66
Table 26: Bridge Energy Loss Sensitivity Analysis – Change in Peak Flood Level (m)	67
Table 27: Initial Water Level Sensitivity Analysis – Change in Peak Flood Level (m)	68
Table 28: Results of Climate Change Impact Analysis – Change in Peak Flood Level (m)	71

LIST OF FIGURES

Figure 1: Study Area
Figure 2: Catchment Topography
Figure 3: Pits and Pipes Stormwater Network
Figure 4: Rainfall Gauge Locations
Figure 5: Historical Rainfall Isohyets November 2018 Event
Figure 6: Cumulative Rainfall November 2018 Event
Figure 7: Burst Intensities and Frequencies November 2018 Event
Figure 8: Community Consultation Responses Map
Figure 9: Community Consultation Analysis
Figure 10: WBNM Hydrologic Model Layout
Figure 11: TUFLOW Model Mannings Roughness
Figure 12: TUFLOW Model Schematisation
Figure 13: Water Level Records Curl Curl Gauge (213426)
Figure 14: Water Level Records Greendale Creek Brookvale Flow Gauge (213499)
Figure 15: Reporting Locations
Figure 16: Pipe Capacity Assessment
Figure 17: Preliminary Flood Planning Area

Appendix C

Figure C1: Calibration Results November 2018
Figure C2: Flood Level Hydrograph (Curl Curl Lagoon at Griffin Road bridge 213426)
Figure C3: November 2018 Event Validation Comparison Overview
Figure C4: November 2018 Event Validation Comparison (Extent 1)
Figure C5: November 2018 Event Validation Comparison (Extent 2)
Figure C6: November 2018 Event Validation Comparison (Extent 3)

Appendix D

Figure D1: Peak Flood Depths and Levels - 50% AEP Event
Figure D2: Peak Flood Depths and Levels - 20% AEP Event
Figure D3: Peak Flood Depths and Levels - 10% AEP Event
Figure D4: Peak Flood Depths and Levels - 5% AEP Event
Figure D5: Peak Flood Depths and Levels - 2% AEP Event
Figure D6: Peak Flood Depths and Levels - 1% AEP Event
Figure D7: Peak Flood Depths and Levels - 0.5% AEP Event
Figure D8: Peak Flood Depths and Levels - 0.2% AEP Event
Figure D9: Peak Flood Depths and Levels - PMF Event
Figure D10: Peak Flood Velocities - 50% AEP Event
Figure D11: Peak Flood Velocities - 20% AEP Event
Figure D12: Peak Flood Velocities - 10% AEP Event
Figure D13: Peak Flood Velocities - 5% AEP Event
Figure D14: Peak Flood Velocities - 2% AEP Event
Figure D15: Peak Flood Velocities - 1% AEP Event
Figure D16: Peak Flood Velocities - 0.5% AEP Event
Figure D17: Peak Flood Velocities - 0.2% AEP Event
Figure D18: Peak Flood Velocities - PMF Event

Appendix E

Figure E1: Hydraulic Hazard (FDM) - 5% AEP Event

Figure E2: Hydraulic Hazard (FDM) - 1% AEP Event

Figure E3: Hydraulic Hazard (FDM) - PMF Event

Figure E4: Hydraulic Hazard (ADR) - 5% AEP Event

Figure E5: Hydraulic Hazard (ADR) - 1% AEP Event

Figure E6: Hydraulic Hazard (ADR) - PMF Event

Figure E7: Hydraulic Categories - 5% AEP Event

Figure E8: Hydraulic Categories - 1% AEP Event

Figure E9: Hydraulic Categories - PMF Event

Figure E10: Flood Planning Constraint Categories

Appendix F

Figure F1: SES Reporting Locations

Figure F2: Flood Level Hydrograph: Location SES1 – Griffin Road Bridge

Figure F3: Flood Level Hydrograph: Location SES2 – Harbord Road

Figure F4: Flood Level Hydrograph: Location SES3 - Manuela Place

Figure F5: Flood Level Hydrograph: Location SES4 - Brighton Street

Figure F6: Flood Level Hydrograph: Location SES5 – Abbott Road

Figure F7: Flood Level Hydrograph: Location SES6 – Pittwater Road

Figure F8: Flood Level Hydrograph: Location SES7 – Gulliver Street

Figure F9: Flood Level Hydrograph: Location SES8 – Consul Road

Figure F10: Flood Level Hydrograph: Location SES9 – McKillop Road

Appendix G

Figure G1: Climate Change Impact – 0.5% AEP compared to 1% AEP Event

Figure G2: Climate Change Impact – 0.2% AEP compared to 1% AEP Event

Figure G3: Climate Change Impact – 1% AEP Event with 0.4 m Sea Level Rise

Figure G4: Climate Change Impact – 1% AEP Event with 0.9 m Sea Level Rise